United States Environmental Protection Agency Region V **POLLUTION REPORT**

Date: Thursday, July 16, 2009

From: Brian Kelly, OSC EPA Region 5 Records Ctr.

To: Linca M. Nachowicz, U.S. EPA

Mark Durno, EPA

Beverly Kush, U.S. EPA Michael Browning, START Maryjane Adamo, U.S. EPA Patrick Hamblin, U.S. EPA Brian Schlieger, U.S. EPA Michael Chezik, U.S. DOI

Jeffrey Bonkoski, Trenton FD Joe Walczak, MDEQ Dan Yordanich, MDEQ Edward Novak, MDEQ Erin Trwin, Wayne County

Susan Thompson, Wayne County Raymond Wojtowicz, Wayne County

Jack Ghannam, Wayne County

Jason El-Zein, U.S. EPA

David Chung, U.S. EPA - HO

Barbara Carr, U.S. EPA Carol Ropski, U.S. EPA Tracy Johnson, U.S. EPA John Maritote, U.S. EPA Mick Hans, U.S. EPA

Jane Mackey, Congressman Conyers

Dave Michalak, Trenton FD

Paul Owens, MDEO Richard Conforti, MDEQ Tracy Kecskemeti, MDEQ

Mark Hammond, Wayne County

Mayor Gerald R. Brown, City of Trenton

Randy Schoen, City of Trenton

Subject: Continuation of Transformer Draining

DSC Trenton Trenton, MI Latitude: 42.1636 Long:tude: -83.1703

POLREP No.: 6 Site #:

B5KV

Start Date:

Reporting Period: 7/6/2009 - 7/16/2009 **D.O.** #:

TO-03

Mob Date:

5/12/2009 5/12/2009 Response Authority: CERCLA **Response Type:**

Time-Critical Non NPL

Completion Date:

MIN 000 510 214

NPL Status: Incident Category:

Removal Action

CERCLIS ID #: RCRIS ID #:

Contract #

PR-R5-09-10107

Site Description

The DSC-Trenton Site (aka Detroit Steel Company formerly McLouth Steel) is a former steel production facility located at 1491 West Jefferson Avenue, Trenton, Michigan.

See previous PCLREPs for details.

Current Activities

U.S. EPA has completed draining 59 of 86 transformers for a total of 26,000 gallons of PCB oil.

U.S. EPA also began to ship, for disposal, the PCB oil drained from the transformers. Five loads of PCB oil, a total of 15,892 gallons of oil, have been shipped to Clean Harbors Deer Park, L.P., 2027 Independence Parkway South, LaPorte, TX 77571.

Another 11,100 gallons of PCB oil is being stored in an on site frac tank pending disposal.

Planned Removal Actions

The draining of transformers is expected to be completed by July 22. U.S. EPA will then begin to move and package for dispose the 3,700 capacitors.

Next Steps

- 1) Continue draining transformers,
- 2) Dispose of transformer oils,
- 3) Begin the removal and disposal packaging of capacitors,
- 4) Mobilize crane to move capacitors.

Key Issues

The environmental problems outlined in the site \square s closure plan are beyond the scope of this removal action. The On-Scene Coordinator has requested U.S. EPA \square s Remedial Section determine whether DSC should be scored for the NPL.

Estimated Costs *

| | Budgeted | Total To Date | Remaining | % Remaining |
|---------------------------|--------------|------------------|--------------|----------------|
| Extramural Costs | | | | |
| ERRS - Cleanup Contractor | \$825,000.00 | \$201,500.00 | \$623,500.00 | 75.58% |
| START | \$25,000.00 | \$13,939.00 | \$11,061.00 | 44.24% |
| Intramural Costs | | | | |
| USEPA | \$15,000.00 | \$11,000.00 | \$4,000.00 | 26.67% |
| | | | | |
| Total Site Costs | \$865,000.00 | \$226,439.00 | \$638,561.00 | 73.82% |

^{*} The above accounting of expenditures is an estimate based on figures known to the OSC at the time this report was written. The OSC does not necessarily receive specific figures on final payments made to any contractor(s). Other financial data which the OSC must rely upon may not be entirely up-to-date. The cost accounting provided in this report does not

necessarily represent an exact monetary figure which the government may include in any claim for cost recovery.

epaosc.net/dsetrenton